



## State of Utah

# Department of Natural Resources

MICHAEL R. STYLER Executive Director

# Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representativ	es Present During the Inspection:
Company	Russell Hardy
OGM	Steve Demczak Environmental Scientist III

# **Inspection Report**

Permit Number:	C0150015
Inspection Type:	COMPLETE
Inspection Date:	Thursday, August 10, 2006
Start Date/Time:	8/10/2006 10:00:00 AM
End Date/Time:	8/10/2006 1:00:00 PM
Last Inspection:	Tuesday, July 25, 2006

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 80's

InspectionID Report Number: 1043

Types of Operations

Reprocessing

Accepted by: pgrubaug

8/29/2006

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO SESSER OPERATIONS

Site: EMERY DEEP MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Cı	urr	en	t /	Αc	re	aa	es

5,408.00	<b>Total Permitted</b>
289.60	<b>Total Disturbed</b>
	Phase I
3	Phase II
	Phase III

#### Mineral Ownership

Other

✓ Federal
✓ Underground

□ State
□ Surface

□ County
□ Loadout

✓ Fee
□ Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Conditions: Emery Deep has one permit condition. The permittee must submit water quality data in an electronic format through the Electronic Data Input web site.

No violations pending.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Monday, August 21, 2006

Inspector ID Number: 39

Permit Number: C0150015 Inspection Type: COMPLETE

Inspection Date: Thursday, August 10, 2006

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
   Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		$\checkmark$	
2.	Signs and Markers	<b>✓</b>			
3.	Topsoil	<b>V</b>		<b>✓</b>	
4.a	Hydrologic Balance: Diversions	<b>V</b>		<b>✓</b>	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		<b>V</b>	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		<b>V</b>	
4.d	Hydrologic Balance: Water Monitoring	V		<b>✓</b>	
4.e	Hydrologic Balance: Effluent Limitations	✓		<b>✓</b>	
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches	<b>✓</b>			
7.	Coal Mine Waste, Refuse Piles, Impoundments	<b>✓</b>		<b>✓</b>	
8.	Noncoal Waste	<b>V</b>			
9.	Protection of Fish, Wildlife and Related Environmental Issues	<b>V</b>			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	✓			
13.	Revegetation	✓			
14.	Subsidence Control	✓			
15.	Cessation of Operations	<b>V</b>			
16.8	Roads: Construction, Maintenance, Surfacing	✓			
16.b	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	V			
18.	Support Facilities, Utility Installations	✓		~	
19.	AVS Check	✓			
20.	Air Quality Permit	✓			
21.	Bonding and Insurance	✓		<b>✓</b>	
22.	Other	П	П	П	

Permit Number: C0150015 Inspection Type: COMPLETE

Inspection Date: Thursday, August 10, 2006

Page 3 of 3

# 1. Permits, Change, Transfer, Renewal, Sale

The permittee has submitted one amendment and exploration plans for review. The permittee has requested an approval for complete subsidence for two pillar sections and to conduct minor explorations. The minor exploration review is scheduled for completion by the end of September. The pillar subsidence amendment is incomplete and more additional information will be submitted from the permittee. No review date can be given until all information is submitted.

#### 3. Topsoil

Topsoil piles were inspected. I found no signs of erosion from wind or water. The 4th east topsoil piles have vegetation; the Emery Mine old topsoil piles have less vegetated growth.

# 4.a Hydrologic Balance: Diversions

The diversions were spot-checked and complied with the R645 requirements.

# 4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds were inspected by the permittee for the second quarter. No hazardous conditions were reported.

# 4.c Hydrologic Balance: Other Sediment Control Measures

Silt fences were spot-checked and were functioning as designed.

### 4.d Hydrologic Balance: Water Monitoring

The permittee has submitted first quarter water data to the Division.

### 4.e Hydrologic Balance: Effluent Limitations

The permittee is in the process of getting new UPDES permit.

#### 7. Coal Mine Waste, Refuse Piles, Impoundments

The permitee inspected the refuse pile for the first and second quarter. No hazardous conditions were reported. The report was P.E. certified.

#### 18. Support Facilities, Utility Installations

No new facilities were constructed since the last inspection.

#### 21. Bonding and Insurance

The insurance will expire on October 5, 2006. The accord form met the minimum requirements of the R645 Coal Rules.